

SELLER'S DISCLOSURE NOTICE

©Texas Association of REALTORS®. Inc. 2022

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which exceed the minimum disclosures required by the Code.

Section 1. The Property has the items marked below: (Mark Yes (Y), No (N), or Unknown (U).)

This notice does not establish the items to be conveyed. The contract will determine which items will & will not convey.

Item	Υ	N	U
Cable TV Wiring	X		
Carbon Monoxide Det.	X		
Ceiling Fans	X		
Cooktop	X		
Dishwasher	×		
Disposal	×		
Emergency Escape Ladder(s)		×	
Exhaust Fans	X		
Fences	X		
Fire Detection Equip.	X		
French Drain	X		
Gas Fixtures	X		
Liquid Propane Gas:		X	
-LP Community (Captive)		x	
-LP on Property		X	

Item	Υ	N	ح
Natural Gas Lines	X		
Fuel Gas Piping:	X		
-Black Iron Pipe	X		
-Copper	X		
-Corrugated Stainless Steel Tubing	×		
Hot Tub		X	
Intercom System	×		
Microwave	X		
Outdoor Grill		X	
Patio/Decking	X		
Plumbing System	X		
Pool	X		
Pool Equipment	X		
Pool Maint. Accessories	×		
Pool Heater	X		

Item	Υ	N	U
Pump: sump grinder			X
Rain Gutters	X		
Range/Stove	X		
Roof/Attic Vents		X	
Sauna		×	
Smoke Detector	X		
Smoke Detector - Hearing Impaired		×	
Spa	X		
Trash Compactor		X	
TV Antenna			X
Washer/Dryer Hookup	X		
Window Screens		X	
Public Sewer System	X		

Item	Υ	N	U	Additional Information				
Central A/C	X			3 electric gas number of units: 3				
Evaporative Coolers		X		number of units: 0 or N/A				
Wall/Window AC Units		X		number of units: 0 or N/A				
Attic Fan(s)			X	if yes, describe:				
Central Heat	X			electric 3 gas number of units: 3				
Other Heat		X		if yes, describe: 0 or N/A				
Oven	X			number of ovens:electric x gas other:				
Fireplace & Chimney	X			1 wood 2 gas logs mock other:				
Carport		X		attached _o_ not attached				
Garage	X			x attached not attached 2 doors/ 3 car spots				
Garage Door Openers	X			number of units: 2 doors number of remotes: 4				
Satellite Dish & Controls		X		owned leased from: 0 or N/A				
Security System	X			X owned leased from: ADT				

(TXR-1406) 07-10-23	Initialed by: Buyer:	_ , and Seller: (// , ,	Page 1 of 7

Fax: (214) 520-4443

Concerning the Property at

23 Carter Ct Allen, TX 75002

Solar Panels				X		ow	ned		leased f	rom:			(O or N/A		
Water Heater			X			ele	ctri	X	gas	other	:			number of units:	3	
Water Softener				X		ow	ned		leased f	rom:			0	or N/A		
Other Leased Items(s)				X	if	yes,	des	crib	e:				0	or N/A		
Underground Lawn Sprinkle	r		X		×	(au	tom	atic	manı	ual a	rea			ered North, South, West	side	
Septic / On-Site Sewer Facil	ity			X										-Site Sewer Facility (TXR-14		
Water supply provided by: Was the Property built before (If yes, complete, sign, a Roof Type: Is there an overlay roof of covering)?yes _X no	e 19 ind a over	78? attac	h T	yes XR-´	no <u>></u> 1906 co	un uncei	kno nin	wn g lea	ad-based	d pair	nt h	aza	ard	ls).	oxima s or	ıte) roof
Are you (Seller) aware of defects, or are need of repair Please see annotations in Section 2. Are you (Selle if you are aware and No (No. 1997).	any r? the	/ of _ye insp	the s X ecti	no on i	If yes, or report	for	ribe ider	(att	ach add ed issue	itiona es an	als ds	hee sub	ets se	if necessary): quent repairs		
Item	Υ	N	1	Ite	m					Υ	I	J		Item	Υ	N
Basement	•	X			oors					X	+	4		Sidewalks	+ •	X
Ceilings		X			oundatio	n / 9	Slah	(c)		^	_	<		Walls / Fences	X	
		×			erior W		olab	(5)			-	_		Windows	^	+
Doors											>	_				X
Driveways		X			ghting F						_	(Other Structural Components		X
Electrical Systems Exterior Walls		X			umbing oof	Sys	tem	S			>	(-	+
If the answer to any of the ite Office floor has chair scr Inspection report noted c Section 3. Are you (Selle and No (N) if you are not a	ratch rack er)	in ma	irks one	fro of	m using the ret	g im tainii	prop ng v	oer valls	wheels s on the	on fl wes	loo st s	r side	2	.,	e aw	/are
Condition						Υ	N	1 [Condit	ion					Υ	N
Aluminum Wiring						† •	X	1	Radon						+ •	>
Asbestos Components							X	1	Settling						X	_
Diseased Trees: oak wilt							X	† †	Soil Mo		ent				-	×
Endangered Species/Habita		Pro	ert	,			X	1					ure	e or Pits		X
Fault Lines				<u>, </u>			X	1						e Tanks		X
Hazardous or Toxic Waste							X	1	Unplatt							X
Improper Drainage							X	1	Unreco							X
Intermittent or Weather Sprin	าตร						X	1						nsulation		X
Landfill	igo						X	1						Due to a Flood Event		X
Lead-Based Paint or Lead-B	250	d Pt	Ha	7arc			X	1	Wetlan		_					X
Encroachments onto the Pro			. I IG	Zaic	15		X	 	Wood F			ОР	CIL	у	+	
Improvements encroaching	•	•	s' nr	One	rtv			 			atio		of t	ermites or other wood	+	X
Improvements encloacing (JII U	u ICI	o hi	ope	ı ty		X		destroy							>
Located in Historic District							~	┧						יוטי) or termites or WDI	×	+
							X	┧							+^	
Historic Property Designation							_	┧	Previou			e 0	ı V	VDI damage repaired		X
Previous Foundation Repair	<u>s</u>						X	ı L	rieviol	is Lile	es_					X

(TXR-1406) 07-10-23

and Seller:

Initialed by: Buyer: _

23 Carter Ct Concerning the Property at Allen, TX 75002

Previous Roof Repairs	X		T
Previous Other Structural Repairs		×	S
Previous Use of Premises for Manufacture of Methamphetamine		×	

Termite or WDI damage needing repair	X
Single Blockable Main Drain in Pool/Hot Tub/Spa*	×

If the answer to any of the items in Section 3 is yes, explain (attach additional sheets if necessary): As noted in August inspection report, roof looked mostly good but had sections that needed repair. This included loose shingles and the top ridge cap repair. This was repaired by Adaptive Roofing LLC. TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT in May 2020 identifed previous treatment for Subterranean Termites. All Safe Pest Control has maintained service of the home since 2020 and has seen NO Termite activity *A single blockable main drain may cause a suction entrapment hazard for an individual. Section 4. Are you (Seller) aware of any item, equipment, or system in or on the Property that is in need of repair, which has not been previously disclosed in this notice? yes X no If yes, explain (attach additional sheets if necessary): Please see August 2024 inspection report and annotations documenting associated repairs Section 5. Are you (Seller) aware of any of the following conditions?* (Mark Yes (Y) if you are aware and check wholly or partly as applicable. Mark No (N) if you are not aware.) Ν X Present flood insurance coverage. X Previous flooding due to a failure or breach of a reservoir or a controlled or emergency release of water from a reservoir. Previous flooding due to a natural flood event. X X Previous water penetration into a structure on the Property due to a natural flood. X partly in a 100-year floodplain (Special Flood Hazard Area-Zone A, V, A99, AE, wholly AO, AH, VE, or AR). partly in a 500-year floodplain (Moderate Flood Hazard Area-Zone X (shaded)). Located wholly X Located wholly partly in a floodway. Located wholly partly in a flood pool. X Located wholly partly in a reservoir. X If the answer to any of the above is yes, explain (attach additional sheets as necessary):

*If Buyer is concerned about these matters, Buyer may consult Information About Flood Hazards (TXR 1414).

For purposes of this notice:

"100-year floodplain" means any area of land that: (A) is identified on the flood insurance rate map as a special flood hazard area, which is designated as Zone A, V, A99, AE, AO, AH, VE, or AR on the map; (B) has a one percent annual chance of flooding. which is considered to be a high risk of flooding; and (C) may include a regulatory floodway, flood pool, or reservoir.

"500-year floodplain" means any area of land that: (A) is identified on the flood insurance rate map as a moderate flood hazard area, which is designated on the map as Zone X (shaded); and (B) has a two-tenths of one percent annual chance of flooding, which is considered to be a moderate risk of flooding.

"Flood pool" means the area adjacent to a reservoir that lies above the normal maximum operating level of the reservoir and that is subject to controlled inundation under the management of the United States Army Corps of Engineers.

(TXR-1406) 07-10-23

Initialed by: Buyer: and Seller: NB

Page 3 of 7

23 Carter Ct Concerning the Property at Allen, TX 75002

"Flood insurance rate map" means the most recent flood hazard map published by the Federal Emergency Management Agency under the National Flood Insurance Act of 1968 (42 U.S.C. Section 4001 et seq.).

"Floodway" means an area that is identified on the flood insurance rate map as a regulatory floodway, which includes the channel of a river or other watercourse and the adjacent land areas that must be reserved for the discharge of a base flood, also referred to as a 100-year flood, without cumulatively increasing the water surface elevation more than a designated height.

"Reservoir" means a water impoundment project operated by the United States Army Corps of Engineers that is intended to retain

Section 6 provider,	or delay the runoff of water in a designated surface area of land. 6. Have you (Seller) ever filed a claim for flood damage to the Property with any insurance including the National Flood Insurance Program (NFIP)?* yes _x no _ If yes, explain (attach sheets as necessary):
Even	es in high risk flood zones with mortgages from federally regulated or insured lenders are required to have flood insurance. when not required, the Federal Emergency Management Agency (FEMA) encourages homeowners in high risk, moderate and low risk flood zones to purchase flood insurance that covers the structure(s) and the personal property within the ure(s).
Administ	7. Have you (Seller) ever received assistance from FEMA or the U.S. Small Business tration (SBA) for flood damage to the Property? yes _X no If yes, explain (attach additional necessary):
	3. Are you (Seller) aware of any of the following? (Mark Yes (Y) if you are aware. Mark No (N) e not aware.)
<u>Y N</u>	Room additions, structural modifications, or other alterations or repairs made without necessary
<u> </u>	permits, with unresolved permits, or not in compliance with building codes in effect at the time.
<u>x</u>	Homeowners' associations or maintenance fees or assessments. If yes, complete the following: Name of association: Not Applicable
	Manager's name: Phone:
	Manager's name: Phone: and are: mandatory voluntary Any unpaid fees or assessment for the Property? yes (\$) no If the Property is in more than one association, provide information about the other associations below or attach information to this notice.
<u>X</u>	Any common area (facilities such as pools, tennis courts, walkways, or other) co-owned in undivided interest with others. If yes, complete the following: Any optional user fees for common facilities charged? yes no If yes, describe:
_ <u>x</u>	Any notices of violations of deed restrictions or governmental ordinances affecting the condition or use of the Property.
<u>x</u>	Any lawsuits or other legal proceedings directly or indirectly affecting the Property. (Includes, but is not limited to: divorce, foreclosure, heirship, bankruptcy, and taxes.)
<u>×</u>	Any death on the Property except for those deaths caused by: natural causes, suicide, or accident unrelated to the condition of the Property.
X	Any condition on the Property which materially affects the health or safety of an individual.
<u>x</u>	Any repairs or treatments, other than routine maintenance, made to the Property to remediate environmental hazards such as asbestos, radon, lead-based paint, urea-formaldehyde, or mold. If yes, attach any certificates or other documentation identifying the extent of the remediation (for example, certificate of mold remediation or other remediation).
<u>X</u>	Any rainwater harvesting system located on the Property that is larger than 500 gallons and that uses a public water supply as an auxiliary water source.
(TXR-1406	S) 07-10-23 Initialed by: Buyer: , and Seller: JLB , Page 4 of 7

Raymond Leon & Associates, LLC, 5827 Del Roy Dr Dallas TX 75230 Ray Mach

Concerning the Prop	perty at	23 Carter Ct Allen, TX 75002								
X The Pro	•	in a propane gas system service area owned by a propane distribution system								
	Any portion of the Property that is located in a groundwater conservation district or a subsiden district.									
	of the items in Section	8 is yes, explain (attach additional sheets if necessary):								
Note: There is a util	ity easement for the su	apport of a lift station on the survey plat. 23 Carter Ct has a	lift station							
located at the front	of the property.									
persons who reg	gularly provide insp	have you (Seller) received any written inspection ections and who are either licensed as inspectors? X yes no If yes, attach copies and complete the follow	or otherwise							
Inspection Date	Туре	Name of Inspector	No. of Pages							
August 3rd 2024	Home Inspection	ADRIAN BUTLER TREC#23094 LUIS DELGADO TREC#24807	49							
May 30th 2020	WDI (Wood Destroying Insect)		3							
August 3rd 2024	Limited Mold Testing	Steven Petersen (MAC #0164) at THE PROVIDENT GROUP	12							
Homestead Wildlife Mana	agement	which you (Seller) currently claim for the Property: Senior Citizen Disabled Agricultural Disabled Veteran omestead and Senior Unknown								
	you (Seller) ever file e provider? yes <u>x</u> r	ed a claim for damage, other than flood damage, to	the Property							
example, an insu	rance claim or a set	received proceeds for a claim for damage to the tlement or award in a legal proceeding) and not used was made? yes <u>x</u> no lf yes, explain:	the proceeds							
detector requirem or unknown, explain Inspection report m *Chapter 766 of installed in accommoding performing your area, you	ents of Chapter 766 I. (Attach additional she arked No, but was counted the Health and Safety Coordance with the requirer mance, location, and power to may check unknown about the second sec	ode requires one-family or two-family dwellings to have working smokements of the building code in effect in the area in which the dwellinger source requirements. If you do not know the building code requirements ove or contact your local building official for more information.	x yes. If no e detectors is located, nts in effect							
family who will impairment fron seller to install	reside in the dwelling is n a licensed physician; and smoke detectors for the he	oke detectors for the hearing impaired if: (1) the buyer or a member of hearing-impaired; (2) the buyer gives the seller written evidence of the seller written evidence of the seller written at the effective date, the buyer makes a written requesting-impaired and specifies the locations for installation. The parties to be detectors and which brand of smoke detectors to install.	the hearing quest for the							

Raymond Leon & Associates, LLC, 5827 Del Roy Dr Dallas TX 75230 Phone: (214) 520-4443 Fax Mach Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com Fax: (214) 520-4443

Initialed by: Buyer:

Page 5 of 7

(TXR-1406) 07-10-23

JLB

and Seller:

Natural Gas: Atmos Energy

Phone Company:

Propane:

Internet:

Not Used currently

Not Used currently

AT&T - Fiber Internet

sign Envelope ID. CCBFE094-AFTA-4026-ADD4-BDETCE927FDC		
Concerning the Property at	23 Carter Ct Allen, TX 75002	
Seller acknowledges that the statements in this notice including the broker(s), has instructed or influenced material information.		· ·
JEFFREY L BAPPETT 12/12/2024		
Signature of Seller Date	Signature of Seller	Date
Printed Name:	Printed Name:	
ADDITIONAL NOTICES TO BUYER:		
(1) The Texas Department of Public Safety maintains determine if registered sex offenders are located <u>https://publicsite.dps.texas.gov</u> . For information of neighborhoods, contact the local police department.	in certain zip code areas. To search the	e database, visi
(2) If the Property is located in a coastal area that is feet of the mean high tide bordering the Gulf of N Act or the Dune Protection Act (Chapter 61 or 63 construction certificate or dune protection permit r local government with ordinance authority over information.	Mexico, the Property may be subject to the 3, Natural Resources Code, respectively) a may be required for repairs or improvements.	e Open Beaches and a beachfron ents. Contact the
(3) If the Property is located in a seacoast territory Commissioner of the Texas Department of Interequirements to obtain or continue windstorm a required for repairs or improvements to the Pracegarding Windstorm and Hail Insurance for Department of Insurance or the Texas Windstorm Insurance	nsurance, the Property may be subjected in the subjected	ct to additiona apliance may be eview <i>Information</i>
(4) This Property may be located near a military instal compatible use zones or other operations. Inform available in the most recent Air Installation Comp for a military installation and may be accessed or county and any municipality in which the military install	ation relating to high noise and compatib atible Use Zone Study or Joint Land Use the Internet website of the military instal	ole use zones is e Study prepared
(5) If you are basing your offers on square footage items independently measured to verify any reported in	•	ould have those
(6) The following providers currently provide service to the	Property:	
Electric: Shell Energy - ESIID 10443720006149268	phone #: (833) SHELL-HN	٨
Sewer: City of Allen	phone #: 214.509.4560	
Water: City of Allen	phone #: 214.509.4560	
Cable: Not Used currently	phone #: Not Applicable	
Trash: City of Allen	phone #: 214.509.4560	

(TXR-1406) 07-10-23 Initialed by: Buyer: _____, ____ and Seller: _____, ____ Page 6 of 7

phone #: 888-286-6700

phone #:

phone #:

phone #:

Not Applicable

Not Applicable

800.288.2020 Available 24/7

Concerning the Property at	23 Carter Ct Allen, TX 75002	
· ·	Seller as of the date signed. The brokers have relied ason to believe it to be false or inaccurate. YOU AI CHOICE INSPECT THE PROPERTY.	
The undersigned Buyer acknowledges receipt of the foregoi	ng notice.	
Signature of Buyer Date	Signature of Buyer Da	ate
Printed Name:	Printed Name:	

(TXR-1406) 07-10-23

Initialed by: Buyer: ___

and Seller:

Page 7 of 7

JLB